



This is our installation guide for our surface mount basins.






Run a line of clear wet area silicon around the underside of the basin 10mm back from the edge.


Run another line of clear wet area silicon 20mm back from the waste hole.





Press basin down into benchtop and remove excess silicon using wax and grease remover and soft cloth.

04



Install waste in a compliant manner. Waste must be hand tight only and not overtightened with tools.

Got a question? Drop us a line, we're here to help!

info@noodco.com.au

noodco.com.au